

Your Ref. No. CBT/UET/01 Dated:

07-06-23

(BS 1881-116)



# COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	Specimens received on:		/6/20	)23	Tested on:	07-0	)6-23	in dry/wet condition			Ċ	jester j
Sr. No.	Mark*	Cas DD	•	Date*	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)	Ultimate Ioad (Imp.Tons)		Water Absorpti on (%)	Remarks
1	Slab (5000 Psi)	9	4	2023	6x6x6		8.4	36	83	5164		Non Engraved
2	Slab (5000 Psi)	9	4	2023	6x6x6		8.2	36	81	5040		Non Engraved
3	Slab (5000 Psi)	9	4	2023	6x6x6		8.6	36	70	4356		Non Engraved
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

 $\underline{\textbf{Note:}}$  Above results pertain to the unsealed samples supplied to the laboratory



To: H.M. Ahsan Saif

Resident Engineer, The Engineer Representative (VELOSI) AIOU, Sahiwal

Project: Construction of AIOU Regional Campus Sahiwal. (Contractor: M/s RAILCOP)

Our Ref. No. CL/	CED/ 2102	Dated:	07-06-23	Test Specification
Your Ref. No.	VISP/135/AIOU/SWL/013	Dated:	30/5/2023	(BS 1881-116)

### COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	ens received on:	5	/6/20	)23	Tested on:	07-0	06-23	in dry/wet condition				iester,
Sr. No.	Mark*		Casting Date*		Size	Wet Weight		Area of X-Section		Ultimate Stress	Water Absorpti on (%)	Remarks
	=	DD	MM	YYYY	(in)	(Kg/ gms)	(Kg/ gms)	(Sq. in)	(Imp.Tons)	(psi)	011 (76)	
1	1st Floor Column (5000 Psi)	24	5	2023	6x6x6		8.2	36	63	3920		Non Engraved
2	1st Floor Column (5000 Psi)	24	5	2023	6x6x6		8	36	25	1556		Non Engraved
3	1st Floor Column (5000 Psi)	24	5	2023	6x6x6		8	36	29	1804		Non Engraved
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.

5341 Dr. M. Mazhar



ORIGINAL A carbon copy for the report has been retained in the lab for record.

5343 Dr. M. Mazhar

To: FM (Works Div), SUPARCO Office Works Division

Project: Construction of Staff Hostel PAKSAT MM-1 at SCF-L Kala Shah Kaku Lahore.

Our Ref. No. CL	/CED/ 2103	Dated:	07-06-23	Test Specification
Your Ref. No.	63301(04) Works/Div/SRDCL	Dated:	19/4/2023	(ASTM C39)

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	ens received on:	6	/6/20	)23	Tested on:	07-0	06-23	in dry/we	t condition			je stanj
Sr. No.	Mark*		Casting Date*		Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	1st Floor RCC Column (4000 Psi)	14	4	2023	6Diax12		13.2	28.28	59	4673		Non Engraved
2	1st Floor RCC Column (4000 Psi)	14	4	2023	6Diax12		13.2	28.28	69	5465		Non Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory





To: FM (Works Div), SUPARCO Office Works Division

Project: Construction of Staff Hostel PAKSAT MM-1 at SCF-L Kala Shah Kaku Lahore.

Our Ref. No. CL	/CED/ 2104	Dated:	07-06-23	Test Specification
Your Ref. No.	63301(04) Works/Div/SRDCL	Dated:	10-05-23	( ASTM C39 )

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	ens received on:	6	6/20	)23	Tested on:	07-0	6-23	in dry/wet condition				iesteri
Sr. No.	Mark*		•	Date*	Size (in)	Wet Weight	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)	Ultimate load (Imp.Tons)		Water Absorpti on (%)	Remarks
1	1st Floor RCC Column (4000 Psi)	14	4	2023	6Diax12	(Rg/ gills) 	(Rg/ gills) 13.2	28.28	(imp:rons) 69	(psi) 5465		Non Engraved
2	1st Floor RCC Column (4000 Psi)	14	4	2023	6Diax12		13.2	28.28	55	4356		Non Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

 $\underline{\textbf{Note:}}$  Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.



Dr. M. Mazhar

### **Director/Dy. Director Concrete Laboratory**



Project: Construction of Toilet Block at PGC-OKARA Campus

Our Ref. No. CL/	CED/ 2105	Dated:	07-06-23
Your Ref. No.	Nil	Dated:	01-06-23

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	ens received on:	1	/6/20	23	Tested on:	07-0	06-23	in dry/wet condition				je stalogija je se
Sr. No.	Mark*		-	Date* YYYY	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	Ground Floor Slab (3000 Psi)	12	5	2023	6Diax12		12.8	28.28	61	4832		Engraved
2	Ground Floor Slab (3000 Psi)	12	5	2023	6Diax12		13	28.28	65	5149		Engraved
3												
4												
5												
6											-	
7											-	
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	Witnessed by:											

#### ninesseu by.

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.

Test Specification (ASTM C39)



Project: Construction of Toilet Block at PGC-OKARA Campus

Our Ref. No. CL/CED/ 2106	Dated:	07-06-23
Your Ref. No. Nil	Dated:	01-06-23

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specim	ens received on:	1	/6/20	23	Tested on:	07-0	6-23	in dry/wet condition				jester j
Sr. No.	Mark*		-	Date* YYYY	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	Ground Floor Slab (3000 Psi)	19	5	2023	6Diax12		13.4	28.28	45	3564		Engraved
2	Ground Floor Slab (3000 Psi)	19	5	2023	6Diax12		13.2	28.28	41	3248		Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

#### Vitnessed by:

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.



Test Specification (ASTM C39)



Project: Construction of Roof Slab Beam , B-1 Line A-3 Grid 1 to 7

Our Ref. No. CL	/CED/ 2107	Dated:	07-06-23
Your Ref. No.	Cylinder Test	Dated:	02-06-23

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:		1/6/2023 Tested on:		07-06-23 i		in dry/wet condition				ES.		
Sr. No.	Mark*	Cas DD	-	Date* YYYY	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)	Ultimate load (Imp.Tons)		Water Absorpti on (%)	Remarks
1	(1:1.87:3.36)	24	5	2023	6Diax12		13.4	28.28	61	4832		Engraved
2	(1:1.87:3.36)	24	5	2023	6Diax12		13.6	28.28	63	4990		Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	ed by:											

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength


4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.

### **Director/Dy. Director Concrete Laboratory**

Test Specification (ASTM C39)



		Dateu.	02-06-23	
Your Ref. No.	Cylinder Test	Dated:	02-06-23	

## **COMPRESSION TEST REPORT**

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:		1/6/2023 Tested on:		07-06-23		in dry/wet condition				ieste g		
Sr. No.	Mark*		•	Date* YYYY	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	(1:1.48:2.60)	25	5	2023	6Diax12		13.2	28.28	43	3406		Engraved
2	(1:1.48:2.60)	25	5	2023	6Diax12		13	28.28	67	5307		Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

#### Witnessed by:

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprerssive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.

(ASTM C39)



Project: Construction of University of Sahiwal, District Sahiwal.

Our Ref. No. CL/	CED/ 2109	Dated:	07-06-23	Test Specification
Your Ref. No.	DCS/GM/UOS/2023/0526/783	Dated:	26/5/2023	(ASTM C39)

### COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:		31/5/2023		023	Tested on:	07-06-23		in dry/wet condition				iester s
Sr. No.	Mark*	Cas DD	•	Date* YYYY	Size	Wet Weight	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	3000 Psi	18	5	2023	(in) 6Diax12		(r.g/ gms) 13	28.28	(imp. rons) 65	(psi) 5149		Engraved
		_										
2	3000 Psi	18	5	2023	6Diax12		13	28.28	71	5624		Engraved
3	3000 Psi	18	5	2023	6Diax12		13	28.28	57	4515		Engraved
4	4000 Psi	19	5	2023	6Diax12		13	28.28	71	5624		Engraved
5	4000 Psi	19	5	2023	6Diax12		13	28.28	20	1584		Engraved
6	4000 Psi	19	5	2023	6Diax12		12.8	28.28	92	7287		Engraved
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

To:

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory





Project: Construction of Gulberg City Centre (Ramp Grid 5-4/B-A.3) Our Ref. No. CL/CED/ 2110 Dated: 07-06-23 Test Specification Your Ref. No. OCC/CPD/27/182 Dated: (ASTM C39)

## COMPRESSION TEST REPORT

Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:			2/6/20	23	Tested on:	07-0	)6-23	in dry/we	t condition		г. С	ies de la
Sr. No.	Mark*	Cas DD	-	Date* YYYY	Size (in)	Wet Weight (Kg/ gms)	Dry Weight (Kg/ gms)	Area of X-Section (Sq. in)			Water Absorpti on (%)	Remarks
1	5000 Psi	27	5	2023	6Diax12		13.4	28.28	41	3248		Not Engraved
2	5000 Psi	27	5	2023	6Diax12		13.4	28.28	49	3881		Not Engraved
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												
15												
16												
Witness	sed by:											

#### vitnessed by:

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory

1. The laboratory is not responsible for sampling, originality and construction conditions (such as mix proportion, w/c ratio, compaction, curing and quality of ingredients) 2. The test results are recommended to be interpreted in the light of above factors by the engineer.



To:

A carbon copy for the report has been retained in the lab for record.

31/5/2023

5327 Dr. M. Mazhar





Resident Engineer, MASCON Associates (Pvt) Ltd and I	HA CONSULTING										
Project: Establishment of Revenue Academy Lahore, G	roup No. 1 (Main Building	of Revenue Acade	my,								
Hostel Block, Staff Accommodation and Residencies etc.)											
Our Ref. No. CL/CED/ 2111	07-06-23	Test Specification									
Your Ref. No. HA-MAS/RE/RAC/04	Dated:	02-05-23	( )								

# **COMPRESSION TEST REPORT**



Concrete Cubes/Concrete Cylinders/Bricks/Cores/Tuff Tiles/Pavers

Specimens received on:		29/5/2023 Tested on:			07-06-23		in dry/wet condition			Ē		
Sr. No.	Mark*	Cas	ting	Date*	Size	Wet Weight	Dry Weight	Area of X-Section		Ultimate Stress	Absorpti	Remarks
		DD	MM	ΥΥΥΥ	(in)	(Kg/ gms)	(Kg/ gms)	(Sq. in)	(Imp.Tons)	(psi)	on (%)	
1	110				9 x 4.4 x 3	3760	3307	39.6	39	2206	13.7	
2	110				8.9 x 4.4 x 3	3860	3400	39.16	39	2231	13.53	
3	110				8.8 x 4.3 x 2.9	3720	3380	37.84	43	2545	10.06	
4	F16				8.8 x 4.4 x 3	3610	3255	38.72	37	2140	10.91	
5	F16				8.8 x 4.3 x 3	3620	3345	37.84	47	2782	8.22	
6	F16				8.8 x 4.3 x 3	3640	3315	37.84	47	2782	9.8	
7					-	DHE NAME OF THY CORD WHE		F				
8							Contraction of the second					
9						2		<b>7</b>				
10					<	-LA	INRE ?					
11												
12												
13												
14												
15												
16												
Vitness	sed by:							1				

#### Vitnessea by:

Results can also be seen on website https://civil.uet.edu.pk/concrete-laboratory-reports1/

1. \* as engraved on the specimens (if any)

2. \*\* BS3921 requires average of ten clay brick samples for crushing strength and water absorption

3. \*\*\* BS5328 requires mean of two cube sample strength at 28 days as characteristic strength

4. \*\*\*\* ACI318-08 requires mean of two sample (6"diax12" cylinder) strength at 28 days as comprensive strength

Note: Above results pertain to the unsealed samples supplied to the laboratory